HYUNDAI OIL BANK CO. Republic of Korea

10, Tongil-ro, Jung-gu, Seoul, Korea 04527 Phone: +82 2 2004 3000 www.oilbank.co.kr



06 MAR 2019

Mr JongBae Lee Emerson Korea Ltd. 259-1, Daeji-ro, Suji-gu, Yongin-si, Gyeonggi-do, Korea 16882

DearJB Lee,

Subject: GE BN3300 Swapped out towards Emerson's AMS 6500 ATG in Korea

We wish to confirm the following successful Vibration Monitoring System (AMS 6500 ATG) installations, which have been completed in Daesan, Korea.

AMS 6500 ATG Protection System for 2 X GHT Feed Pumps 3 X Compressors (B1601A/B/S)

Hyundai oil bank in Daesan(Korea) got worried because the existing old vibration monitoring system should be replaced. Then we decided to replace and upgrade the obsolete BN3300 with Emerson's AMS 6500 ATG Machinery Health Monitors providing equipment protection on each of our 2 X Feed Pumps in 2017 and 3 X Compressors in 2018. We are now satisfied with that the project was well managed and the system was commissioned in a short period, only 5 days.

Scope of work and supply:

1 X AMS 6500 ATG Protection only for 2 X GHT Feed Pumps

3 X AMS 6500 ATG Protection only for 3 X Compressors (B1601A/B/S)

Integration to DCS (MODBUS/Hard Wiring)

• Engineering, Commissioning and training

We are very pleased with the system so far, everything is working so fine, and we would recommend Emerson's AMS 6500 ATG as Vibration Prediction/Protection system for other highly critical machines throughout our company.

Yours sincerely,

Name: MATOL. OSH.

Title: Cy21.

Hyundai Oil Bank Co.